

# Fluke 975 AirMeter<sup>™</sup>

Five powerful tools in one, with simple one-touch air velocity



# **Technical Data**

#### Use the Fluke 975 AirMeter test tool to:

- Respond to comfort-related calls from occupants.
- Verify the operation of building HVAC control systems.
- Determine whether adequate ventilation exists.
- Monitor air flow and velocity.\*
- Test for dangerous carbon monoxide leaks.
- Perform duct traversals.

#### **Features:**

- Simultaneously measures, logs, and displays temperature, humidity,  $\rm CO_2$ , and  $\rm CO$  on a bright, backlit LCD display
- One-touch air flow and velocity with available probe\*
- Wet bulb and dew point temperature
- % of outside air calculation
- CO<sub>2</sub> and CO field calibration feature
- Self-test function at startup
- Auto-backlight
- Automatically compensates for barometric pressure changes
- Min/Max/Average on all measured and calculated readings
- Multi-language user interface
- Metric or standard units
- Audible and visual threshold alarms
- Extensive discrete or continuous data logging capacity, downloadable to PC via USB interface
- Keypad lock for security
- Included FlukeView Forms® software
- \*Included with Fluke 975V, optional with Fluke 975

上海萨海测量技术有限公司 电话: 021-6236 2960 传真: 021-5235 2321 邮箱: sales@seasy-ist.com 网址: www.seasy-ist.com



## Fluke 975 AirMeter specifications

Feature	Range	Display resolution	Accuracy
Measured specifications			
Temperature	-20 °C to 50 °C (-5 °F to 122 °F)	0.1 °F (0.1 °C)	± 0.9 °C/± 1.62°F from 40 °C to 50 °C ± 0.5 °C/± 1.00°F from 5 °C to 40 °C ± 1.1 °C/± 1.98 °F from -20 °C to 5 °C
Relative humidity	10 % to 90 % RH non-condensing	1 %	± 2 % RH (10 % RH to 90 % RH)
Air velocity	0.50 fpm to 3000 fpm 0.25 m/sec to 15 m/sec	1 fpm (0.005m/sec)	$\begin{array}{l} \pm 4\% \text{ or } 4 \text{ fpm}^* \\ \pm 4 \% \text{ or } 0.02 \text{ m/sec}^* \text{ whichever is greater} \\ \text{*Accuracy specification only valid for velocity readings above 50 fpm.} \end{array}$
CO <sub>2</sub>	0 to 5000 ppm	1 ppm	Warm up time 1 min (5 minutes for full specification) 2.75 $\%$ + 75 ppm
СО	0 to 500 ppm	1 ppm	$\pm$ 5 % or $\pm$ 3 ppm, whichever is greater, @ 20 °C and 50 % RH
Calculated specifications			
Dew point temperature	-44 °C to 50 °C (-47 °F to 122 °F)	0.1 °C (0.1 °F)	$\pm$ 1 °C when temp: -20 °C to 50 °C RH: 40 % to 90 % $\pm$ 2 °C when temp: -20 °C to 50 °C RH: 20 % to 40 % $\pm$ 4 °C when RH: 10 % to 20 %
Wet bulb temperature	-16 °C to 50 °C (3 °F to 122 °F)	0.1 °C (0.1 °F)	$\pm$ 1.2 °C when RH: 20 % to 90 % temp: -20 °C to 50 °C $\pm$ 2.1 °C when RH: 10 % to 20 %
Volume flow rate (in a duct)	0 to 3,965 M <sup>3</sup> /m (0 to 140,000 cfm)	0.001 M <sup>3</sup> /min (1 cfm)	N/A: The volume flow calculation will be a simple average of the data points times the duct area
% outside air (based on temperature)	0 to 100 %	0.1 %	N/A
% outside air (based on $CO_2$ )	0 to 100 %	0.1 %	N/A
General specifications			
Operating temperature: CO and CO <sub>2</sub> sensors	-20 °C to 50 °C (-4 °F to 122 °F)		
Operating temperature: All other functions	-20 °C to 50 °C (-4 °F to 122 °F)		
Storage temperature	-20 °C to 50 °C (-4 °F to 122 °F)		
Humidity	10 % to 90 % (non-condensing)		
Altitude	Up to 2000 m (6562 ft)		
Shock and vibration	MIL-PRF-28800F: Class 2		
Multi-language interface	English, French, Spanish, Portuguese and German		
Battery	Rechargeable Li-Ion (primary), three-AA (backup)		
Data logging	25,000 records (continuous), 99 records (discrete)		
Warranty	Two-years		

## **Ordering Information**

Fluke-975AirMeter™Fluke-975VAirMeter™ with Velocity

Included

AA alkaline batteries (3) Users manual (with safety information) Calibration cap Hard carrying case FlukeView® Forms software Power adapter International power plugs Air velocity probe (Fluke 975V only)

#### **Optional accessories**

ToolPak<sup>™</sup> Magnetic Meter Hanging Kit Fluke-975CK AirMeter Calibration Kit Fluke-975VP AirMeter Air Velocity Probe



上海萨海测量技术有限公司 电话: 021-6236 2960 传真: 021-5235 2321 邮箱: sales@seasy-ist.com 网址: www.seasy-ist.com